

From: [McCarter, Jennifer](#)
To: [Bailey, Treasure](#)
Cc: [Morrison, Kendra](#); [Jacobson, Linda](#); [Churchill, Stephen](#); [jill.parisi](#); [Kilty, Quinn V](#)
Subject: Comanche field update 0811
Date: Wednesday, August 12, 2020 8:42:21 AM

Hi Treasure, All – summary of Tuesday’s work; continuing to monitor water levels to confirm when static/stabilized

- MW-1 well set w/screen across the water in the lower weathered shale/upper fractured shale (25-40ft); water at 28.65
- MW-2 is at 40 ft; continued coring. No alluvium or colluvium, thin layer of topsoil over weathered shale; water at 20ft
- W-2A water 24.43 ft bgs
- W-2B difficulty reading water level due to conductivity; appears to be at 68.55 ft bgs, but will continue to monitor
- W-7 water 4.74 ft bgs
- W-8 dry

Jennifer McCarter, R.E.M.

Xcel Energy

Environmental Analyst

Environmental Services Department

1800 Larimer St., Suite 1300, Denver, CO 80202-1414

P: 303-294-2228 C: 720-810-1220 F: 303-294-2328

E: jennifer.mccarter@xcelenergy.com

XCELENERGY.COM

Please consider the environment before printing this email